

WATERED & WATERLESS URINAL PROGRAM AND RESTROOM AREA ODOR CONTROL
IMPROVE HYGIENE & REDUCE GERMS



SPRAY URINE FREE LIBERALLY ALL OVER THE URINAL SURFACE AREA IN & UNDER & INTO THE DRAIN
THIS WILL CLEAN ALL URINE AND LEAVE A SHINE ON THE UNIT
WIPE DOWN IF NEEDED.

DON'T USE BLEACH IN URINALS WITH THIS PROGRAM



SPRAY URINE FREE OVER THE WALLS & SURFACE AREA AROUND THE URINAL TO REMOVE THE OVERSPASH AND ALSO SPRAY THE FLOOR. ONCE DONE THEN YOU CAN MOP THE FLOOR WITHOUT SPREADING URINE ALL OVER. MORE CONTACT TIME THE BETTER THE RESULT. YOU CAN LEAVE THE WALLS OR WIPE DOWN IF REQUIRED OVER TIME THE TILE GROUT WILL CLEAR OF URIC CYRSTAL



OPEN CAP OF FLOW FRESH GEL & POUR AROUND THE DRAIN & URINAL BASE. AS THE URINAL IS USED THE GEL WILL DILUTE AND GO INTO PIPES FRESHENING THE ODOURS AND ALSO KEEP THE PIPEWORK CLEAR OF URIC ACID



IF YOU ARE USING GEL SCREENS PUT THE GEL SCREEN OVER THE GEL THAT WAS SPREAD EARLIER
WHEN USING FLOW FRESH GEL POUR IT UNDER THE SCREEN



SPRAY URINE FREE ON THE COMMODES IN GENTS AND LADIES BATHROOMS TO CLEAN URINE OFF THE COMMODES. YOU WILL NOTICE THE SPARKLE AND THE PLEASANT ODOR THOROUGHOUT



SPRAY URINE FREE IN THE RESTROOM AREA CORRIDOR AND THEN MOP AS NORMAL
THIS WILL REMOVE URINE IN THE AREA AND KEEP THE AREA SMELLING FRESH. IT WILL CLEAR ALL URINE THAT SPREAD WHILST MOPPING!

YOU WILL NOTICE INSTANT RELIEF FROM BAD URINE ODORS. YOU WILL SEE THE THE GROUT CLEAR. CUSTOMERS WILL NOTICE THE DIFFERENCE.
THERE WILL BE LESS CHANCE OF URINAL BLOCKAGES FROM URIC ACID BY FOLLOWING THE PROCEDURE

REPEAT THE PROCESS ABOVE ON YOUR REGULAR CLEANING ROUTINE- IE EVERY 3 HOURS

YOU WILL NOT NEED AIR FRESHER SYSTEMS AS THE RESTROOMS WILL BE FRESH AND CLEAN

CLEAN RESTROOMS MAKE HAPPY CUSTOMERS!!!!!!!